| Total No. o | of Questions | : | 91 | |
|-------------|--------------|---|----|--|
|-------------|--------------|---|----|--|

P2367

[4758]-512

[Total No. of Pages : 3

T.E. (Mechanical/Automobile) METROLOGYAND QUALITY CONTROL (End Semester) (2012 Pattern) (Semester-I)

| <i>Time</i> : 2 ¹ | /2 Hours] | [Max. Marks : 70 |
|------------------------------|---|------------------|
| | ons to the candidates: | |
| 1) | Neat diagrams must be drawn wherever necessary. | |
| 2) | Figures to the right indicate full marks. | , |
| <i>3) 4)</i> | Use of electronic pocket calculator and steam tables is allowed. Assume suitable data if necessary. | |
| Q1) a) | Explain principle's of Engineering metrology in details. | [6] |
| b) | Write a note on laser interferometer. | [4] |
| | OR | |
| Q2) a) | Explain different methods of measuring flatness. | [6] |
| b) | Differentiate between primary texture and secondary text | ture. [4] |
| Q3) a) | Define Taylor's principle. | [2] |
| b) | Write a note on floating carriage micrometer. | [4] |
| c) | Explain universal measuring machine. | [4] |
| | OR | |
| Q4) a) | Explain principle of interferometry. | [2] |
| b) | Write a note on span gauging. | [4] |
| c) | Explain Automatic inspection system. | [4] |
| Q5) a) | Explain Deming's fourteen points in details. | [8] |
| b) | Explain seven New Quality tools. | [8] |
| | OR | |

- **Q6)** a) Define cost of prevention, cost of appraisal, cost of internal failure & cost of external failure. [8]
 - b) Explain seven quality control tools.

[8]

- **Q7)** a) Explain in detail OC curve and show following element on OC curve[6]
 - i) α-Risk
 - ii) β-Risk
 - iii) AOQ
 - iv) LTPD
 - b) Two machines producing components are checked up for the statistical stability. Draw the 'P' chart for both machines and comment upon the processes. Sample size for both machines are 200. [10]

Machine A

| Sample No. | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|------------|----|----|----|----|----|----|----|----|----|----|
| Defectives | 25 | 28 | 30 | 30 | 20 | 29 | 31 | 26 | 31 | 27 |

Machine B

| Sample No. | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|------------|----|----|----|----|----|----|----|----|----|----|
| Defectives | 11 | 08 | 22 | 15 | 12 | 27 | 10 | 15 | 10 | 02 |

OR

- **Q8)** a) Differentiate between single, double and multiple sampling plan. [6]
 - b) Components are being turned on CNC lathe to a specification of 12.58 ± 0.05mm. Five batches of five components each have been drawn for inspection at 1 hour intervals. The readings are tabulated below. [10]

| Batch 1 | Batch 2 | Batch 3 | Batch 4 | Batch 5 |
|---------|---------|---------|---------|---------|
| 12.62 | 12.63 | 12.62 | 12.61 | 12.59 |
| 12.60 | 12.56 | 12.56 | 12.66 | 12.58 |
| 12.62 | 12.60 | 12.57 | 12.62 | 12.57 |
| 12.61 | 12.59 | 12.58 | 12.61 | 12.59 |
| 12.65 | 12.60 | 12.63 | 12.60 | 12.56 |

- i) Determine the process capability.
- ii) Determine the three-sigma limits for the \bar{X} chart.
- iii) Draw the control chart and give your assessment. Assume the normal distribution and d_2 for group size 5 is 2.326.

Q9) Write short notes on following (Any Three):

[18]

- a) TPM.
- b) Six sigma.
- c) Kanban.
- d) QFD.
- e) JIT.
- f) Poka-yoke.

•••••