Total No. of Questions: 8]		SEAT No.:		
P5019		[4960]-1072		[Total No. of Pages : 2
	M.E.		Design Engg.)	
	MECHANICAL	MEASU	REMENT & C	CONTROL
	(2013	Course) (	Semester - III	)
1) 2)	Hours] ons to the candidates: Answer any 5 questions. Draw neat diagrams who Figures to right indicate	erever necess	ary.	[Max. Marks : 50
4)	Assume suitable data if	necessary.		
<b>Q1)</b> a)	What are the stages of measurement system.			[5]
b)	Explain probable error & standard error.			
<b>Q2)</b> a)	Explain different types of correlation.			[5]
b)	b) Find the most likely production corresponding to rain fall 40" following data.			
	Average	Rainfall 30"	production 500 kg	
	Standard Deviation	5"	100kg	
	Co-efficient of corre	elation = 0.8	3	
<b>Q3)</b> a)	What are properties	of correlati	on co-efficient.	[4]

What are properties of correlation co-efficient. **[4]** Obtain the lines of regression from the data given **[6]** b) 8 X: 5 6 11 4 Y: 12 10 8 7 5

Verify that co-efficient of correlation is geometric mean of two co-efficients of regression.

- **Q4)** a) Explain the working of ultrasonic flow meter stating its applications. [5]
  - b) A copper resistor at 20°C is used to measure the temperature of bearing of a machine. What is the value of maximum resistance if the maximum bearing temp. is not to exceed 150°C. The resistance temperature coefficient is 0.00393/°C at 20°C. [5]
- **Q5)** a) What are the various methods to measure level. Explain capacitance method. [5]
  - b) How do you measure phase angle. [5]
- **Q6)** a) What are the transient response specifications. [5]
  - b) Explain  $P + \Sigma + D$ . Control system. [5]
- Q7) a) Draw Bode's plot for a control system whose transfer function is

$$G(S)H(S) = \frac{80}{S(1+0.025)(1+0.05S)}$$
 [5]

- b) Discuss the resistance temperature properties of a thermister. [5]
- **Q8)** a) Find the stability of a feedback control system  $S^5 + S^4 + 4S^3 + 2S + 1 = 0$ .[5]
  - b) Explain the calibration of a thermocouple. [5]

y2 y2 y