

Total No. of Questions : 9]

SEAT No. :

P2839

[4958]-1012

[Total No. of Pages : 2

T.E.(Mechanical)

METROLOGY AND QUALITY CONTROL

(2012 Course) (End Sem)

Time : 2½ Hours]

[Max. Marks : 70

Instructions to the candidates:

- 1) *All questions are compulsory (Solve Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8, Q.9.)*
- 2) *Neat diagrams must be drawn wherever necessary.*
- 3) *Assume suitable data if necessary.*
- 4) *Use of calculator is allowed.*
- 5) *Figures to the right side indicate full marks.*

Q1) a) Differentiate between systematic errors and random errors. **[5]**

b) State different types of comparators, explain sigma comparator in detail. **[5]**

OR

Q2) a) Describe with neat sketches of auto-collimator and sine bar. **[5]**

b) State different types of linear and angular measuring instruments, explain any two with example. **[5]**

Q3) a) State and explain Taylor's Principle of Gauge Design with example. **[5]**

b) Optical arrangement of interferometer for testing flatness of surfaces. **[5]**

OR

Q4) a) What is surface texture? State different methods to analyze surface trace **[5]**

b) A machine operator needs a gauge for checking the diameter of bores being machined to diameter 20 ± 0.06 mm. What should be the dimensions (diameter) of the gauge if unilateral systems of tolerances are incorporated? Assume gauge tolerance and wear allowance each as 10% of work tolerance. **[5]**

P.T.O.

Q5) a) Explain PDCA & PDSA Cycle. [8]

b) Describe different quality costs. [8]

OR

Q6) a) Write short note on: Juran's Trilogy. [8]

b) Differentiate between Quality Assurance & Quality control. [8]

Q7) a) Ten samples of parts were taken from a production line For 100% inspection, each sample containing 300 parts. The total number of defection was 350. Compute upper and lower control limit [5]

b) Explain analysis on out of control condition referring control charts. [5]

c) Explain in detail with flow chart single sampling and double sampling plan. [8]

OR

Q8) a) A new process is started, and the sum of sample standard deviation for 25 subgroups of size 4 is 750. If the specifications are 700 ± 80 , what is process capability index? what action would you recommend take for four samples factor for centeline = $c_4 = 0.9213$ [6]

b) Ten castings were inspected in order to locate defect in them after in spection total 37 defects were found. Compute control limit for c-Chart. [4]

c) Write note on PPAP and OC curve. [8]

Q9) Write short note on (any four) [16]

a) Cause & effect diagram

b) Pareto diagram

c) Kaizen

d) TPM

e) 5 s

f) J I T

