

Q.1 (a)  $P=8$ , Lap wound,  $A=P$ ,  $N=450$  rpm

$$E_g = 260 \text{ V} \quad \phi = 0.02751 \text{ wb}$$

$$\text{No. of slots} = 140$$

$$E_g = \frac{\phi ZNP}{60A} \quad (01)$$

$$\therefore E_g = \frac{\phi ZN}{60} \Rightarrow Z = \frac{E_g \cdot 60}{\phi \cdot N} = \frac{260 \times 60}{0.02751 \times 450} = 1260 \quad (01)$$

$$\text{conductors/slot} = \frac{1260}{140} = 9 \quad (01)$$

$$(b) E_b = V - I_a R_a \quad (01)$$

$$\therefore V = E_b + I_a R_a \quad (01)$$

$$\therefore V \cdot I_a = E_b I_a + I_a^2 R_a \quad (01)$$

$$P_{in} = P_{arm} + P_{cu}$$

$$P = T\omega \Rightarrow P_{arm} = T \cdot \omega = \frac{2\pi NT}{60} \quad (01)$$

$$E_b I_a = \frac{2\pi NT}{60} \quad (01)$$

$$\therefore \frac{\phi ZNP}{60A} = \frac{2\pi NT}{60}$$

$$\therefore T = \left(\frac{1}{2\pi}\right) \left(\frac{PZ}{A}\right) \phi \cdot I_a = 0.159 \left(\frac{PZ}{A}\right) \cdot \phi \cdot I_a \quad (02)$$


(c) Appropriate applications

i) D.C. shunt motor (02)


ii) D.C. series motor (02)

OR


Q.2 (a) Torque-arm current



Speed-arm current



Speed-torque



D.C. shunt motor

(b)  $P=4$ , Wave wound  $A=2$ , slots = 65, cond./slot = 6

$$Z = 65 \times 6 = 390, \quad \phi = 0.02 \text{ wb}, \quad R_a = 0.15 \Omega$$

$$V = 250 \text{ volts}, \quad I_a = 60 \text{ A} \quad E_b = V - I_a R_a = (250) - (60)(0.15)$$

$$E_b = \frac{\phi ZNP}{60A} \quad (01)$$

$$\therefore E_b = 241 \text{ volts} \quad (03)$$

$$\therefore N = \frac{E_b \cdot 60 \cdot A}{\phi \cdot Z \cdot P} = \frac{241 \times 60 \times 2}{0.02 \times 390 \times 4}$$

$$\therefore N = 926.92 \text{ rpm} \approx 927 \text{ rpm} \quad (02)$$

$= 4, \text{ Lap } A=P, Z=600, N=1200, \phi_T = 47 \text{ mWb}$

$$E_g = \frac{\phi Z N P}{60 A} \text{ (01)}$$


$$= \frac{24 \times 10^{-3} \times 600 \times 1200}{60 \times 4} = 72 \text{ Volts. (01)}$$

ii) For wave wound  $A=2$

$$E_g = \frac{\phi Z N P}{60 A} = \frac{24 \times 10^{-3} \times 600 \times 1200}{60 \times 2} = 144 \text{ Volts (02)}$$

Q.3 (a) Any six significant points of differentiation between slip ring and squirrel cage induction motor (01 each)

(b) Torque - slip characteristics of 3 phase induction motor



Correct Explanation (01)

(c)  $V=440 \text{ V}, f=50 \text{ Hz}, P=4$  (01)

i)  $N_s = \frac{120f}{P} = \frac{120 \times 50}{4} = 1500 \text{ rpm}$  (01)

ii)  $N = N_s(1-s) = (1500)(1-0.04) = (1500)(0.96) = 1440 \text{ rpm}$  (01)

iii)  $f_r = sf = (0.04)(50) = 2 \text{ Hz}$  (01)

iv)  $f_r = sf = f = 50 \text{ Hz}$  (01)

OR

Q.4 (a) Resistance split phase single phase induction motor

- i) circuit diagram (02)      iii) Disadvantages (01)  
 ii) advantages (02)      iv) Applications (01)

(b) Advantages of squirrel cage rotor (02)

Advantages of slip ring rotor (02)

(c)  $V=440 \text{ V}, f=50, P=6$

i)  $N_s = \frac{120f}{P} = \frac{120 \times 50}{6} = 1000 \text{ rpm}$  (01)

ii)  $N = N_s(1-s) = 1000(1-0.04) = 960 \text{ rpm}$  (01)

iii)  $f_r = sf$        $s = \frac{N_s - N}{N_s} = \frac{1000 - 900}{1000} \times 100 = 0.1 \text{ or } 10\%$  (01)

iv)  $f_r = (0.1)(50)$

$f_r = 5 \text{ Hz}$  (01)

Q.5

- a → ii  
 b → iv  
 c → iv  
 d → iii  
 e → ii

(2 each)

- f → ii  
 g → iii  
 h → i  
 i → i  
 j → ii

(2 each)