

G.R. No.

Paper Code - U127-104B (ESE)

MAY 2018/ ENDSEM**F. Y. B. TECH. (COMMON) (SEMESTER - II)****COURSE NAME: BASIC ELECTRICAL ENGINEERING****COURSE CODE: 10174B****(2017 PATTERN)**

Time: [2 Hours]

[Max. Marks: 50]

(*) Instructions to candidates:

- 1) Answer Q.1 OR Q.2, Q.3 OR Q.4 and Q.5.
- 2) Figures to the right indicate full marks.
- 3) Use of scientific calculator is allowed.
- 4) Assume suitable data wherever required.

Q.1) a) A 8 pole wave wound DC shunt motor has 400 conductors and draws a line current of 12 A from the supply. Its field winding takes a current of 2 A. If the flux per pole is 0.05 Wb, calculate the torque developed by an armature and speed of the motor if the back emf developed by motor is 200 V. [6]

b) Draw and explain torque-armature current, speed-armature current and speed-torque characteristics of a dc shunt motor. [6]

c) Explain function of commutator and brushes in D.C. Generator and state material used for these components. [4]

OR

Q.2) a) Derive the torque equation of a dc motor with usual notations. [6]

b) A 4 pole wave connected DC shunt generator has 600 armature conductors and runs at 1200 rpm. This generator has a flux per pole of 6 mWb. Calculate i) the emf induced in the above dc generator ii) Find the speed at which it should be driven to produce the same emf when lap connected [6]

c) State any two significant applications of i) dc shunt motor ii) dc series motor. [4]

Q.3) a) A 6 pole, 3-phase squirrel cage induction motor operates from a 400 V three phase ac supply whose frequency is 50 Hz. Calculate: [4]

- i. Synchronous speed of the motor
- ii. Speed of the motor when the slip is 0.04
- iii. Frequency of the rotor current when the slip is 0.03
- iv. Frequency of the rotor current at standstill

b) State any two applications of i) squirrel cage and ii) slip ring three phase induction motors. [4]

c) Write a note on resistance split phase single phase induction motor with respect to the following points: i) Neat circuit diagram with proper labels ii) Advantages iii) Disadvantages iv) Applications [6]

OR

Q4) a) A three phase slip ring induction motor is wound for 4 poles and is supplied from 415 V, 50 Hz three phase ac supply. Calculate:

- i. Synchronous speed
- ii. Rotor speed, when slip is 8%
- iii. Rotor frequency and percentage slip when rotor runs at 1200 rpm [4]

b) Draw torque-slip characteristics of three phase induction motor and indicate starting torque and full load torque on it. [4]

c) Explain why single-phase induction motor is not self-starting. How is it made self-starting? State any two types of single-phase induction motor. [6]

Q.5) Attempt following multiple choice questions: [10x2=20 marks]

a) For a series R-L circuit if R is 20 Ω , X_L is 15 Ω then power factor of this circuit will be: [2]

- i. 0.8 leading
- ii. zero lagging
- iii. 0.8 lagging
- iv. zero leading

b) For a series R-C circuit if R is $8\ \Omega$, C is 0.05 F and supply frequency is [2]

50 Hz then total impedance Z of this circuit in Ω will be:

- i. $8 + j\ 0.064$
- ii. $8 - j\ 0.064$
- iii. $8 - j\ 15.70$
- iv. $8 + j\ 15.70$

c) According to Kirchhoff's voltage law in any closed loop of a network [2]


- i. The algebraic sum of all the e.m.f.s is zero
- ii. The algebraic sum all the voltage drops is zero
- iii. The algebraic sum of all e.m.f.s and voltage drops is zero
- iv. The algebraic sum of all currents is zero

d) For a single phase A.C. circuit if the supply voltage is 200 V, current [2]

is 2 A and phase angle Φ is 90° then the reactive power will be

- i. 400 VAR
- ii. Zero
- iii. 57.5 VAR
- iv. 92 VAR

e) Find voltage drop across $6\ \Omega$ resistance in the following circuit. [2]



- i. 20 V
- ii. 10 V
- iii. 27 V
- iv. 12 V

- f) The transformation ratio of a single phase 200 V/100 V, 1KVA transformer is _____. [2]
- 1
 - 1.15
 - 2
 - 0.5
- g) In a three phase symmetrical AC circuit, the phasor sum of all three voltages at any instant is: [2]
- infinity
 - zero
 - one
 - none of the above
- h) A transformer has 70 turns on secondary and maximum flux in core is 0.06 Wb. If supply frequency is 60 Hz, induced e.m. f. in secondary will be: [2]
- 932.4 V
 - 1118.88 V
 - 1776 V
 - 1276 V
- i) Full load Copper loss of a transformer is 1000 W. At half load, the copper loss will be: [2]
- 500 W
 - 1000 W
 - 250 W
 - 4000 W
- j) The two-wattmeter method is applicable for measurement of power in [2]
- Both star connected and delta connected balanced load.
 - Only delta connected unbalanced load.
 - Both star connected and delta connected balanced and unbalanced load.
 - None of these.