# [3761]-13

## F. E. Examination - 2010

### BASIC MECHANICAL ENGINEERING

(2003 Course)

Time: 3 Hours

Max. Marks: 100

Instructions:

- (1) Answer Q. 1 or 2, Q. 3 or 4, Q. 5 or 6 and Q. 7 or 8, O. 9 or 10. O. 11 or 12.
- (2) Answers to the two sections should be written in separate books.
- Use of logarithmic tables slide rule, Mollier charts, electronic pocket calculator and steam tables is allowed.
  - (4) Assume suitable data, if necessary.

# SECTION - I

- O.1) (A) Define: Process, Path, State, Cycle, System. [05]
  - Explain Bourdon Pressure Gauge with sketch. (B) [06]
  - The casting of mass 12 kg has original temperature of 200°C. (C) If it loses heat of 801.36 kJ, find final temperature of casting. (Given: Specific Heat of Casting Material = 477 J/kgk). [05]

- Explain First Law of Thermodynamics with an example. O.2)(A) [05]
  - State steady flow energy equation, explain various terms and (B) convert it for nozzle application. [05]
  - Define and explain: PMMI, Isothermal Process, Enthalpy. (C) [06]

| Q.3) | (A) | Draw neat sketch and name various parts of a Refrigerator         |      |
|------|-----|---|------|
|      |     | Cycle.  | [06] |
|      | (B) | State applications of Compressed Air.                             | [05] |
|      | (C) | State classification of Boiler.                                   | [05] |
|      |     | OR  |      |
| Q.4) | (A) | Compare 2-stroke and 4-stroke IC Engine.                          | [05] |
|      | (B) | List any four mounting of Boiler and state their functions.       | [05] |
|      | (C) | Draw sketch and explain Centrifugal Pump.                         | [06] |
| Q.5) | (A) | Describe Hydroelectric Plant with sketch.                         | [06] |
|      | (B) | What is Fin ? Explain types of Fin and list its applications.     | [06] |
|      | (C) | What is Counter Flow and Parallel Flow Heat Exchanger ?           | [06] |
|      |     | OR ald many   |      |
| Q.6) | (A) | Describe Nuclear Power Plant with sketch.                         | [06] |
|      | (B) | Derive expression for heat conduction through composite slab.     | [06] |
|      | (C) | What is Insulator? Why they are needed? State name of Insulators. | [06] |
|      |     | SECTION - II  |      |
| Q.7) | (A) | How drilling machines are classified ?                            | [05] |
|      | (B) | Draw only sketch and show various parts of Lathe Machine.         | [06] |
|      | (C) | Compare Soldering and Brazing.                                    | [05] |
|      |     | Carlant first Law of The Odynamics with an exami                  |      |
|      | (A) | Explain arc welding with its applications.                        | [05] |
| [50] | (B) | State advantages of CNC Machine.                                  | [05] |
| [90] | (C) | Compare Power Sawing and Hand Sawing with its applications.       | [06] |

| Q.9)  | (A)   | State and explain any three modes of failure used in Design. | [06] |
|-------|-------|--|------|
|       | (B)   | State factors considered for selection of material.          | [05] |
|       | (C)   | What are ergonomic considerations of Design ?                | [05] |
|       |       | OR   |      |
| Q.10) | (A)   | Explain Limits and Tolerance with sketch.                    | [06] |
|       | (B)   | Compare hot and cold working of Metal.                       | [05] |
|       | (C)   | What are Aesthetic Considerations??                          | [05] |
| Q.11) | (A)   | Compare Individual and Group Drive.                          | [06] |
|       | (B)   | Explain any one type of Clutch with sketch.                  | [06] |
|       | (C)   | Explain Flexible Coupling with sketch.                       | [06] |
|       |       | OR   |      |
| Q.12  | (A)   | Compare Belt and Gear Drive.                                 | [06] |
|       | (B)   | Explain various types of Keys.                               | [06] |
|       | (C) - | What is Flywheel? State its use and applications.            | [06] |